

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/24/2021

Submitted Date:

12/07/2021

Document Number:

689806707

FIELD INSPECTION FORM

Loc ID 312948 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10677
 Name of Operator: WOLVERINE RESOURCES LLC
 Address: 109 EAST 17TH STREET #430
 City: CHEYENNE State: WY Zip: 82001

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Reeves, Shane		shane@wolverineresources.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222986	WELL	SI	08/01/2019	GW	081-06348	STERRETT 1	SI

General Comment:

Routine FIU follow up inspection. Follow up to inspection from 5/20/2021 document number 689805841. No corrective actions have appear to have been made. Compliance issues remaining:
 no bradenhead access apparent
 dried annual weeds on location
 Additional compliance issues observed during this inspection:
 well overdue for MIT

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	DEBRIS		
Comment:	Dried annual weeds have become debris.		
Corrective Action:	Comply with Rule 606.	Date:	06/26/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:		#		corrective date
Bird Protectors				
Comment:				
Corrective Action:			Date:	
Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:			Date:	
Plunger Lift		# 1		
Comment:				
Corrective Action:			Date:	
Gas Meter Run		# 1		
Comment:				
Corrective Action:			Date:	
Bradenhead		#		

Comment:	No bradenhead access apparent.		
Corrective Action:	Install bradenhead access and/or means of monitoring bradenhead pressure.	Date:	06/28/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 222986 Type: WELL API Number: 081-06348 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 12/21/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689806708	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600404