

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2021

Submitted Date:

12/03/2021

Document Number:

696203405**FIELD INSPECTION FORM**Loc ID 452807 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1001 17TH STREET #1900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452807	LOCATION	AC			-	CC 0697-03-07 Pad	RI

General Comment:

On 12/1/2021, Reclamation Specialist Trujillo conducted an interim reclamation inspection at Laramie Energy's CC 0697- 03-07 Pad Location in Garfield County, Colorado.

This inspection is also a followup to:

#692401699 dated 12/11/2019;

#696202114 dated 12/8/2020;

#696202676 dated 5/14/2021;

#696202924 dated 7/12/2021

and #696203329 dated 11/2/2021 to document compliance with the following corrective actions:

1002.f: Stormwater

1003.b: Interim Reclamation

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and Corrective actions.

New observed compliance issues per this inspection:

-Good Housekeeping

Refer to the "Good Housekeeping", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment:

Various concrete waste/debris was observed stored and/or partially buried on the southeast corner of the pad, as well as within the cut slope of the Location.

Corrective Action:

Remove and properly dispose concrete waste/debris.

Date: 12/10/2021Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? Fail

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? _____ Segregated soils have been replaced? Fail

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment See "COGCC Comments" for comments regarding reclamation.

Corrective Action Comply with Rule 1003 rules

Date 06/02/2019

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Previous inspections documented that BMPs to protect and stabilize the cut and fill slopes of the Location are missing or insufficient; fill slopes constructed with a steep grade, with rocky subgrade material.</p> <p>Inspections required the Operator to comply with 1002.f.</p> <p>It was observed in this inspection that control measures to protect/stabilize the fill slopes of the Location remain missing or insufficient per good engineering practices.</p> <p>Location remains out of compliance with Rule 1002.f</p>						
<p>Corrective Action: Comply with Rule 1002.f.(2) and install BMPs in accordance with good engineering practices.</p>						<p>Date: 01/10/2021</p>
<p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

COGCC Comments

Comment	User	Date
<p>RECLAMATION COMMENTS</p> <p>Previous inspections documented that the Location was out of compliance with 1003 requirements. Inspections required Operator to comply with 1003 rules and perform interim reclamation. Inspection #696203093 also observed that additional wells have been permitted on the Location (approved 4/20/2021); Form 2 COAs require compliance with the Notice to Operators: Interim Reclamation Procedures for Delayed Operation (dated January 5, 2017).</p> <p>It was observed in this inspection that interim reclamation has not been conducted in accordance with 1003 Rules; areas not needed for production have not been decompacted, recontoured/regraded and reclaimed; Location has not been reduced to 2 acres per the 2A Location Permit #401387622; Location ~6 acres in size. No NTO for delayed IR has been submitted/approved</p> <p>Corrective action has not been addressed and remain applicable.</p>	trujilloam	12/03/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402886869	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595820
696203406	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595815