

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402802718

Date Received:  
09/29/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10736  
Name of Operator: ADVANCED WIRELESS COMMUNICATIONS LLC  
Address: 5500 RAIL RD  
City: FARMINGTON State: NM Zip: 87402  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Krysten Moore</u>	<u>5054860045</u>	<u>krysten@advancedwirelessllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903525  
Inspection Date: 08/06/2021 FIR Submit Date: 08/11/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ADVANCED WIRELESS COMMUNICATIONS LLC Company Number: 10736  
Address: 5500 RAIL RD  
City: FARMINGTON State: NM Zip: 87402

LOCATION - Location ID: 306981

Location Name: SLUGGER-N33N8W Number: 18NWSE County: LA PLATA  
Qtrqr: NWSE Sec: 18 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.101870 Longitude: -107.756610

FACILITY - API Number: 05-067-00 Facility ID: 289332

Facility Name: SLUGGER Number: 2  
Qtrqr: NWSE Sec: 18 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.101870 Longitude: -107.756610

CORRECTIVE ACTIONS:

1 ☒ CA# 154776

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o. by 9/13/2021. Berms need to be stabilized to prevent erosion.

Date: 09/13/2021

Response: CA COMPLETED Date of Completion: 09/24/2021

Operator Comment: Sediment that had fallen down into berm was pulled out and used to rebuild the containment area.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 154777

Corrective Action: -As numerous untreated Russian knapweeds were observed, corrective action to control weeds by 7/31/2021 is not adequately addressed. Therefore corrective action to control weeds needs to be immediately addressed.

Date: 07/31/2021

Response: CA COMPLETED

Date of Completion: 08/17/2021

Operator Comment: Flowing knapweeds had been removed on 7/12/21 and 7/13/21. After follow up inspection it was found that more had grown up and a few were missed on first removal effort. Sent crew back 8/17/21 to removed remaining knapweeds. Also around 8/13/21, Arkoma had their operator spot spray for the knapweed as well.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: We have instructed our operators to remove an thistles that may emerge in the future so that we can stay ahead of the flowering and spreading/outbreak of these invasive weeds.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: krysten Moore

Signed: \_\_\_\_\_

Title: VP

Date: 9/29/2021 11:34:09 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402802718	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files