

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402812014

Date Received:  
09/15/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

| Contact Name             | Phone | Email                      |
|--------------------------|-------|----------------------------|
| <u>Jones, Tammy</u>      |       | <u>tajones@hilcorp.com</u> |
| <u>Shorty, Priscilla</u> |       | <u>pshorty@hilcorp.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903354  
Inspection Date: 07/02/2021 FIR Submit Date: 07/06/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326226

Location Name: HUBER-LEWIS-N34N8W Number: 4NWSE County: LA PLATA  
Qtrqtr: NWSE Sec: 4 Twp: 34N Range: 8W Meridian: N  
Latitude: 37.241040 Longitude: -107.746630

FACILITY - API Number: 05-067-00 Facility ID: 216068

Facility Name: HUBER-LEWIS Number: 2-4  
Qtrqtr: NWSE Sec: 4 Twp: 34N Range: 8W Meridian: N  
Latitude: 37.241040 Longitude: -107.746630

CORRECTIVE ACTIONS:

1  CA# 152434

Corrective Action: -Revegetation needs to be conducted within the southern project area. Corrective action is back-dated to 4/1/2020 to document duration of non-compliance as corrective action is not addressed. Soil remediation may be needed. Livestock exclusion may be needed.

Date: 04/01/2020

Response: CA COMPLETED Date of Completion: 09/13/2021

Operator Comment: Attached are pictures of the seeding and mulching that was completed on the subject well's location.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**2**  CA# 152435

Corrective Action: -Install stormwater (ie: BMPs) and erosion controls (ie: mulch, ebiodegradable erosion blanket, etc.). Controls need to be selected, sized, installed, and maintained according to good engineering practices. Corrective action is back-dated to 1/10/2020 to document duration of non-compliance as stormwater erosion remains uncontrolled within the project area.

Date: 01/10/2020

Response: CA COMPLETED

Date of Completion: 07/27/2021

Operator  
Comment:

Attached are pictures of the work completed to satisfy the BMP portion of the INC.  
On 7-24-21.  
Crew cleaned out rock check dams, bladed the access road, pulled ditches and re crowned, Re-set wattles and cleaned out silted in area in front of wattles

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Resubmitting due to not including set of BMP photos in the first submission.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 9/15/2021 9:47:14 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <b>Document Number</b> | <b>Description</b>       |
|------------------------|--------------------------|
| 402812014              | FIR RESOLUTION SUBMITTED |
| 402812020              | Huber-Lewis 2-4 Photos   |
| 402812021              | Huber-Lewis 2-4 Photos2  |

Total Attach: 3 Files