

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402842062

Date Received:

10/14/2021

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Huntington, Heather

hhuntington@enduringresources.com

Walter, Kyle

kwalter@enduringresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903641

Inspection Date: 09/09/2021

FIR Submit Date: 09/13/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC

Company Number: 10663

Address: 1050 17TH STREET SUITE 2500

City: DENVER State: CO Zip: 80265

LOCATION - Location ID: 326660

Location Name: WHEELER-M34N10W Number: 13NWNE County: LA PLATA

Qtrqr: NWNE Sec: 13 Twp: 34N Range: 10W Meridian: M

Latitude: 37.196938 Longitude: -107.882148

FACILITY - API Number: 05-067- -00 Facility ID: 261590

Facility Name: WHEELER Number: 13-4

Qtrqr: NWNE Sec: 13 Twp: 34N Range: 10W Meridian: M

Latitude: 37.196938 Longitude: -107.882148

CORRECTIVE ACTIONS:

1 ☒ CA# 155771

Corrective Action: -Spot seeding needs to be conducted on portions of the cut and fill slopes with little to no desirable vegetation. Corrective action date: 10/31/2021.

Date: 10/31/2021

Response: CA COMPLETED

Date of Completion: 10/13/2021

Operator Comment: SEED WAS BROADCAST

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2  CA# 155772

Corrective Action: -Stabilize erosion within the project area by replacing and maintaining stormwater BMPs such that they are adequate to prevent sediment discharge and erosion within the project area. Erosion controls such as mulch need to be installed and maintained until bare soils are stabilized with desirable perennial vegetation. Corrective action date: 10/13/2021.

Date: 10/13/2021

Response: CA COMPLETED

Date of Completion: 10/13/2021

Operator  
Comment: SEE ATTACHED PHOTOS OF CORRECTIVE ACTION

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: HEATHER HUNTINGTON

Signed: \_\_\_\_\_

Title: PERMITTING TECH

Date: 10/14/2021 11:24:05 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402842062	FIR RESOLUTION SUBMITTED
402842083	CA PHOTOS

Total Attach: 2 Files