



Franvilo 22-35



Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a