

FORM
6Rev
11/20State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Replug By Other Operator

Document Number:

402926471

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10254

Contact Name: Shannon Chollett

Name of Operator: RED MESA HOLDINGS/O&G LLC

Phone: (970) 250-0130

Address: 5619 DTC PARKWAY - STE 800

Fax:

City: GREENWOOD State: CO Zip: 80111

Email: shannon.chollett@state.co.us

For "Intent" 24 hour notice required,

Name: Labowskie, Steve

Tel: (970) 946-5073

COGCC contact:

Email: steve.labowskie@state.co.us

Type of Well Abandonment Report: ☐ Notice of Intent to Abandon ☒ Subsequent Report of Abandonment

API Number 05-067-09364-00

Well Name: JUMBO (OWP)

Well Number: 1A

Location: QtrQtr: NENW

Section: 27

Township: 33N

Range: 12W

Meridian: N

County: LA PLATA

Federal, Indian or State Lease Number:

Field Name: RED MESA

Field Number: 72890

Only Complete the Following Background Information for Intent to Abandon

Latitude: 37.080319

Longitude: -108.138927

GPS Data: GPS Quality Value: 0.9 Type of GPS Quality Value: Accuracy in Meters Date of Measurement: 07/23/2021

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes ☐ No Estimated Depth:Fish in Hole: ☐ Yes ☐ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
DAKOTA	3200	3290	07/19/2021	BRIDGE PLUG	3009
GREENHORN	3068	3116	07/19/2021	BRIDGE PLUG	3009

Total: 2 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	17	13+3/8	J-55	48	0	250		250	0	VISU
1ST	11	8+5/8	J-55	24	0	1340	250	1340	0	VISU
2ND	7+7/8	5+1/2	J-55	15.5	0	3350	300	3350	2070	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 3009 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 10 sks cmt from 2543 ft. to 2443 ft. Plug Type: CASING Plug Tagged: ☐
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 1385 ft. with 95 sacks. Leave at least 100 ft. in casing 1340 CICR Depth
 Perforate and squeeze at 805 ft. with 55 sacks. Leave at least 100 ft. in casing 759 CICR Depth
 Perforate and squeeze at 300 ft. with 90 sacks. Leave at least 100 ft. in casing 250 CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 8 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 0 ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: 6
 Surface Plug Setting Date: 07/20/2021 Cut and Cap Date: 07/26/2021

*Wireline Contractor: The Wireline Group *Cementing Contractor: DUCO Inc.

Type of Cement and Additives Used: Class G

Flowline/Pipeline has been abandoned per Rule 1105 ☒ Yes ☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Shannon Chollett

Title: OWP Engineer Date: _____ Email: shannon.chollett@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

Condition of Approval

COA Type**Description**

0 COA	

Attachment List

Att Doc Num**Name**

402927951	CEMENT JOB SUMMARY
402927952	WELLBORE DIAGRAM
402927953	WIRELINER JOB SUMMARY
402927954	OPERATIONS SUMMARY

Total Attach: 4 Files

General Comments

User Group**Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)