

OIL AND GAS CONSERVATION COMMISSION  
OF THE STATE OF COLORADO

00300253

e in duplicate for Patented and Federal lands.  
e in triplicate for State lands.

RECEIVED

MAR 23 1970

5. LEASE DESIGNATION AND SERIAL NO.

OIL &amp; GAS CONS. COMM.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Fehringier

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Pebble

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

28-12N-52W

12. COUNTY OR PARISH

Logan

13. STATE

Colorado

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL  
WELL ☐GAS  
WELL ☐

OTHER

DRY HOLE

2. NAME OF OPERATOR

W. R. Pfeifer

3. ADDRESS OF OPERATOR

6135 Brentwood, Arvada, Colorado 80002

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface 660' from East line and 1,980' from North line

At proposed prod. zone

Same

14. PERMIT NO.

69 664

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4,494' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent  
to this work.)Well was drilled to total depth of 5,276' and electric logs run. Since no significant shows of  
oil or gas were found, the well was plugged and abandoned on March 16, 1970, as follows:

15 sacks cement from 235' to 265'

10 sacks cement from surface to 30'

Intervening depths were filled with heavy mud.

5/8/70 - Checked location, pits not filled, location  
not leveled, do not release bond. Jim  
called operator on 5/11/70.

4/9/70 - Called W.R. Pfeifer Jr. about pits &amp; location.

7/24/70 - Called W.R. Pfeifer on pits &amp; location.

8/13/70 - Checked location, P+A OK, release bond. Jim

DVR	<input checked="" type="checkbox"/>
FJP	<input checked="" type="checkbox"/>
HHM	<input checked="" type="checkbox"/>
JAM	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>

18. I hereby certify that the foregoing is true and correct

SIGNED

George L. Gear

TITLE

Agent for W. R. Pfeifer

DATE

March 20, 1970

(This space for Federal or State office use)

APPROVED BY

W. Rogers

TITLE

DIRECTOR

O &amp; G CONS. COMM.

DATE

MAR 24 1970

CONDITIONS OF APPROVAL, IF ANY: