

RECEIVED

MAR 22 1968



00283858

ND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands. File in triplicate for State lands.

COLO. OIL & GAS

5. LEASE DESIGNATION AND SERIAL NO. CONS. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL [] GAS WELL [] OTHER Dry Hole
2. NAME OF OPERATOR Don M. Rounds and B. W. Drilling, Inc.
3. ADDRESS OF OPERATOR 925 Petroleum Club Bldg., Denver, Colorado
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' from E. Line & 660' from S. Line At proposed prod. zone
5. LEASE DESIGNATION AND SERIAL NO. CONS. COMM. SW SE Sec. 22-12N-56W
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Buczkowskyj
9. WELL NO. 1
10. FIELD AND POOL, OR WILDCAT Wildcat
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
12. COUNTY OR PARISH Weld
13. STATE Colorado
14. PERMIT NO. 67-489
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4911' gr. 4918' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF [] PULL OR ALTER CASING [] WATER SHUT-OFF [] REPAIRING WELL []
FRACTURE TREAT [] MULTIPLE COMPLETE [] FRACTURE TREATMENT [] ALTERING CASING []
SHOOT OR ACIDIZE [] ABANDON [] SHOOTING OR ACIDIZING [] ABANDONMENT [X]
REPAIR WELL [] CHANGE PLANS []
(Other) [] (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work Plugged and Abandoned December 9, 1967.

The hole was filled with heavy drilling mud. A 15 sack cement plug set in the base of surface pipe. A 10 sack cement plug set in the top of surface pipe.

The location has been restored, pits backfilled to the surface owners satisfaction, evidenced by Release of Damages dated 2-28-68.

Table with 2 columns and 5 rows: DVR, FJP, HHM, JAM, JJD. Checkmarks are present in the second column for FJP, HHM, JAM, and JJD.

6/27/68 - Checked location, Pt A OK, Jim

18. I hereby certify that the foregoing is true and correct

SIGNED Don M. Rounds TITLE Owner DATE 3-21-68

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE Director DATE MAR 25 1968

CONDITIONS OF APPROVAL, IF ANY: