

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402780194

Date Received:

08/13/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Atwater, Bonnie</u>	<u>432-755-0212</u>	<u>batwater@ogrisop.com</u>
<u>O'Shields, Charlie</u>	<u>940-682-5030</u>	<u>coshields@ogrisop.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>efitzgerald@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695103936

Inspection Date: 02/02/2021

FIR Submit Date: 02/02/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308693

Location Name: NEW ELK-633S68W Number: 35NENE County: LAS ANIMAS

Qtrqtr: NENE Sec: 35 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.132270 Longitude: -104.957990

FACILITY - API Number: 05-071-00 Facility ID: 279154

Facility Name: NEW ELK Number: 35-01

Qtrqtr: NENE Sec: 35 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.132270 Longitude: -104.957990

CORRECTIVE ACTIONS:

1 CA# 146248

Corrective Action: COMPLY WITH RULE 606, REMOVE UNUSED EQUIPMENT.

Date: 05/02/2021

Response: CA COMPLETED

Date of Completion: 08/11/2021

Operator Comment: THE UNUSED EQUIPMENT WAS REMOVED FROM THE LOCATION.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 146249

Corrective Action: COMPLY WITH RULE 606 AND 608.e.

Date: 05/02/2021

Response: CA COMPLETED

Date of Completion: 08/11/2021

Operator
Comment: THE IMPACTED SOIL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED. ALL VALVES, PIPES AND FITTINGS ARE SECURLY FASTENED. THE FLUID ACCUMULATION WAS REMOVED FROM THE CONTAINMENT.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 146250

Corrective Action: COMPLY WITH RULE 1002.f. AND Comply with general provisions of the oil and gas act for wildlife protection. AND SB-181.

Date: 02/09/2021

Response: CA COMPLETED

Date of Completion: 08/11/2021

Operator
Comment: THE IMPACTED SOIL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED. ALL VALVES, PIPES AND FITTINGS ARE SECURLY FASTENED. THE FLUID ACCUMULATION WAS REMOVED FROM THE CONTAINMENT.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 8/13/2021 2:18:16 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402780194	FIR RESOLUTION SUBMITTED
402780207	PHOTO LOG

Total Attach: 2 Files