

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Location entrance is adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 262596 Type: WELL API Number: 123-20764 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI and is in the process of PA, Form 42 (PA) Doc # 402910094

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 02/11/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 295 Fluid Type: GAS

End Surf Csg Pressure: 1

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Rip Rap	Pass			
		Tracking Pad	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 2/3/2022 at approximately 1010 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to Inspection Doc # 699304865. Operator: Oxy/Kerr McGee Location: Ballantine 4-30A API # 05-123-20764 County: Weld While there, I observed a wellsite, in the process of being PA. During this inspection the following possible compliance issue has been addressed: 1002.f.(2)F Vehicle Tracking: Tracking pad has been installed in addition to the rip rap that was already in place. See attached photos. Location: frozen and snow covered, Weather: clear and cold. Erin Joseph Oxy Regulatory Consultant Contacted me on 2-2-2022 about the CA I issued about vehicles tracking of dirt/mud when leaving location, He said that they had been sweeping regularly and were on top of the issue and placed tracking pads on 2-1-2022 before the day ended. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	02/03/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304884	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654483