

Inspection Photos
Location Name: Yellico #3-2
Location ID: 322221



Photo 1 loc pic



Photo 2 TNK BTRY NFPA placards faded



Inspection Photos
Location Name: Yellico #3-2
Location ID: 322221



Photo 3 loc pic



Photo 4 stained soil and mechanical issue take load out line.

Inspection Photos
Location Name: Yellico #3-2
Location ID: 322221



Photo 5 Mechanical issue gear box bearing leaking and creating stained soil under motor skid