

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402949733

Date Received:

02/07/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|--------------------|--------------|-----------------------|
| ATWATER, BONNIE | 432-755-0212 | batwater@ogrisop.com |
| GIENA WARD | 719-220-4041 | gward@ogrisop.com |
| O'SHIELDS, CHARLIE | 940-682-5030 | coshields@ogrisop.com |
| GEE, GREG | 903-987-0353 | ggee@ogrisop.com |

COGCC INSPECTION SUMMARY:

FIR Document Number: 695104890

Inspection Date: 10/06/2021

FIR Submit Date: 10/06/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-4978
VILLAGE

LOCATION - Location ID: 308316

Location Name: HILL RANCH-634S67W Number: 34SESE County: LAS ANIMAS

Qtrqtr: SESE Sec: 34 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.033560 Longitude: -104.867300

FACILITY - API Number: 05-071- -00 Facility ID: 266156

Facility Name: HILL RANCH Number: 34-16

Qtrqtr: SESE Sec: 34 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.033560 Longitude: -104.867300

CORRECTIVE ACTIONS:

1 CA# 156482

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.

Date: 10/13/2021

Response: CA COMPLETED

Date of Completion: 01/11/2022

Operator Comment: THE PUMPING UNIT ENGINE WAS REPLACED AND NO LEAKS HAVE BEEN DETECTED. THE FLUID ACCUMULATION WAS REMOVED FROM CONTAINMENT. THE IMPACTED SOIL NEXT TO THE CONCRETE BASE WAS REMOVED FROM THE LOCATION AND THE SELF-INSPECTION PROCESS WAS REVIEWED. THE STAIN ON THE CONCRETE BASE WAS ALSO REMOVED.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 156483

Corrective Action: Install sign to comply with Rule 605.a. (NOTE: THE NEW RULES REQUIRE THE API # TO BE POSTED ON NEW SIGNS).

Date: 01/06/2022

Response: CA COMPLETED

Date of Completion: 11/05/2021

Operator Comment: THE LOCATION SIGN WAS REPLACED IN ACCORDANCE WITH THE NEW RULES.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA WARD

Signed: _____

Title: ENVIRONMENTAL TECHNICIAN

Date: 2/7/2022 2:14:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| | |
|-----------|-------------------------------------|
| 402949753 | SEE ATTACHED PHOTO LOG FOR DETAILS. |
|-----------|-------------------------------------|

Total Attach: 1 Files