

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

C-040175

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

McCallum

8. FARM OR LEASE NAME

9. WELL NO.

73

10. FIELD AND POOL, OR WILDCAT

McCallum Unit

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 18, T9N, R78W, 6th P.M.

12. COUNTY OR PARISH

Jackson

13. STATE

Colorado

1.

OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 3312 - Durango, Colorado

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)

At surface

1780' FSL, 1730' FSL (NW SE)



00272395

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

8264' DF, 8253' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to kill the subject well with water and plug and abandon as follows:

Set 150' regular cement plug in 4 1/2" O.D., 11.6# casing from 5750' to 5900' RB to cover perforations from 5782' to 5882'. Set 50' cement plug from 4760' to 4810' after cutting 4 1/2" O.D., casing at 4785'. Set 30' cement plug from 400 to 450' in 7 5/8" O.D., surface casing set at 429'. Set 6' cement plug in top of surface casing with 4" by 10' marker, 6' cemented in top of surface casing.

DVR	
WRS	
HMM	
JAM	
FJP	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>
FILE	

18. I hereby certify that the foregoing is true and correct

SIGNED F. E. ELLIS Original Signed By

TITLE Asst. District Manager

DATE 7-16-65

(This space for Federal or State office use)

APPROVED BY [Signature]

TITLE Director

DATE JUL 20 1965

CONDITIONS OF APPROVAL, IF ANY:

OIL & GAS COMM.

*See Instructions on Reverse Side