

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402947076

Date Received:  
02/03/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699804047

Inspection Date: 01/24/2022

FIR Submit Date: 01/24/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334982

Location Name: FEDERAL-67S96W Number: 11NWN County: \_\_\_\_\_

Qtrqr: NWNE Sec: 11 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.457979 Longitude: -108.074995

FACILITY - API Number: 05-045- -00 Facility ID: 334982

Facility Name: FEDERAL-67S96W Number: 11NWN

Qtrqr: NWNE Sec: 11 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.457979 Longitude: -108.074995

CORRECTIVE ACTIONS:

1 ☒ CA# 159388

Corrective Action: Operators will prevent and minimize adverse impacts to wildlife resources.

Date: 01/31/2022

Response: CA COMPLETED

Date of Completion: 01/31/2022

Operator  
Comment:

Vent pipe covered with screen mesh and secured. CA completed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 159389

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 02/08/2022

Response: CA COMPLETED

Date of Completion: 02/03/2022

Operator Comment: Location will be graded and ruts will be removed once site dries out and site conditions allow. TEP continues to restrict access to locations during muddy conditions and continues to educate employees and contractors regarding the importance of minimizing traffic during muddy conditions. See attached response.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Cas # 159388 and 159389 have been completed / addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP ENV

Date: 2/3/2022 4:08:23 PM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402947076	FIR RESOLUTION SUBMITTED
402947080	Correspondence
402947081	NO traffic during muddy conditions

Total Attach: 3 Files