

TEP
Valley Farms D
Location # 335534



location



location

TEP
Valley Farms D
Location # 335534



Location/truck loading fluid from tanks



Debris

TEP
Valley Farms D
Location # 335534



Debris (tumbleweeds) next to burners on separators that are running.



Lack of stabilization/erosion

TEP
Valley Farms D
Location # 335534



Lack of stabilization/erosion




Some of cut slope has a blanket

TEP
Valley Farms D
Location # 335534



Lack of stabilization/erosion



Truck loading fluid from valves at back of tanks, not the valves in the buckets.