

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2022

Submitted Date:

02/15/2022

Document Number:

691201561

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 Graber, Candice (Nikki) 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1675 BROADWAY, STE 2800
 City: DENVER State: CO Zip: 80202
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
Maria Petrocco		Maria@petroccolaw.com	Complainant
LLC, Marcom	208-201-8280	PrimaryContractor@marcomllc.net	
Gorka, Ray		RGorka@kpk.com	KPK environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478005	SPILL OR RELEASE	CL	12/31/2020		-	H. Huett Consolidation Release	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

On February 14, 2022 COGCC conducted an inspection of the H. Huett Consolidation (Facility ID 478005) spill area in response to Complaint Document #402952008. The complaint, filed by the Attorney for the Landowner, states:

"The Wright Family has a working farm located at 2645 CR 23, Fort Lupton, CO. This farm has a well on it operated by KP Kauffman. The well is called the Joseph L. Huett C1 well and there was a leak. KP Kauffman dug a hole to repair the leak. The hole was dug over a year ago and there has been no remediation. The large hole is very dangerous and the tenant farmer had to cover the hole with a tarp and put stakes around it to prevent the workers from falling into the large open unprotected hole dug by KP Kauffman."


Based on verbal communication with the complainant the complaint was assigned to the Facility #8 Consolidation Line spill (Facility ID 469095).

COGCC personnel and KPK primary contractor personnel met with the landowner to discuss the issue. Three unremediated KPK spills are present on his property:

Facility #8 Consolidation Line (Facility ID 469095)
 E. Stieber Consolidation (Facility ID 480275)
 H. Huett Consolidation (Facility ID 478005)

The large excavation noted in the complaint is at the H. Huett Consolidation (Facility ID 478005), the E. Stieber Consolidation (Facility ID 480275) is actively being worked by excavation crews, and the Facility #8 Consolidation Line (Facility ID 469095) is idle.

Based on a review of available documents on COGIS and site conditions the H. Huett Consolidation (Facility ID 478005) excavation was opened during spill response on or around 9/14/2020; the excavation has intermittently been worked and expanded, never backfilled. Per the open Remediation Project #16135, vertical or lateral extent of impacts have not been defined.



Location

Lease Road:			
Type			
comment:	Adjacent to county road.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 580px; height: 20px;" type="text"/>
Corrective Action:	<input style="width: 580px; height: 20px;" type="text"/>
Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:	Orange construction fencing up and signage present at excavation.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 478005 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Based on a review of available documents on COGIS and site conditions the H. Huett Consolidation (Facility ID 478005) excavation was opened during spill response on or around 9/14/2020; the excavation has intermittently been worked and expanded, never backfilled. Per the open Remediation Project #16135, vertical or lateral extent of impacts have not been defined.

Corrective Action: Operator shall submit a stand alone site specific remedial action plan with dates indicating a timeline for remediation of this release via Form 27 within 14 days of this inspection 3/1/2022. Date: 03/01/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201562	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5665448