

Inspection Photos

02/14/2022

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335538

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335538



Photo 1: Photo taken from the cut slopes behind the separator equipment; erosion blankets have been maintained.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335538



Photo 2: Photos taken from exposed areas of the cutslopes (photo left) and the eastern slopes of the Location (photo right). Unable to find evidence that control measures to protect and stabilize the slopes of the Location were installed or maintained. Photo insert top-right shows areas where rill erosion is evident on the eastern slopes.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335538



February 14, 2022
39.5275543N 107.649463W



February 14, 2022
39.5264777N 107.6463295W

Photo 3: Photos taken from the tank battery on the east end of the Location. Photo shows examples of unused equipment observed stored within the tank battery containment BMP.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335538



Photo 4: Photo shows example of noxious weeds (Russian Olive) that remain evident on the Interim Areas of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335538



February 14, 2022
39.52585016N 107.64277781W

Photo 5: Photo taken from the northern end of the production area, facing south east. Areas of the production pad not covered with snow do not appear to be stabilized, and are at risk of vehicle tracking and sediment transport.