

Inspection Photos

02/14/2022

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335534

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335534



Photo 1: Photo taken from the east end of the Location, facing east. Photo shows Operator has implemented erosion control blankets on only a single section of the upper cut slopes of the Location. Control measures to protect and stabilize the remaining cut slopes left and right of the blanket seen in the photo, as well as slopes below the blanket.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335534



Photo 2: Photos taken from the cut slopes. Photos provide examples showing control measures to protect/stabilize the cut slopes of the Location remain missing or insufficient; erosion degradation evident.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335534



Photo 3: Photos taken from the slopes on the north end of the Location. Photo example showing that the blankets installed on the Location have not been installed in accordance with good engineering practices; blankets have not been properly trenched/anchored and backfilled.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335534



February 14, 2022
39.5439833N 107.664632W

Photo 4: Photo taken from the outlet on the west end of the Location; outlet has been re-installed with rip-rap and geotextile armoring.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources