

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402961330

Date Received:

02/21/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701900291

Inspection Date: 12/15/2021

FIR Submit Date: 01/28/2022

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 332813

Location Name: WOLF-64N66W Number: 31SESE County: _____

Qtrqr: SESE Sec: 31 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.263360 Longitude: -104.813540

FACILITY - API Number: 05-123-00 Facility ID: 332813

Facility Name: WOLF-64N66W Number: 31SESE

Qtrqr: SESE Sec: 31 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.263360 Longitude: -104.813540

CORRECTIVE ACTIONS:

1 CA# 159401

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 12/15/2021

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 02/09/2022

Operator
Comment:

Wolf 44-31 well was plugged and reclaimed in 2014, and in 2018, Suncor disturbed the former wellhead area and access road. Available aerial images show the previous reclamation before re-disturbance. The associated production facility was abandoned and reclaimed in June 2021 after the last well was plugged in spring 2021. This reclamation was in the first growing season which had record heat and very little precipitation. However, since a location assessment was already performed, PDC will reseed prior to the Spring growing season. CA complete.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

Wolf 44-31 well was plugged and reclaimed in 2014, and in 2018, Suncor disturbed the former wellhead area and access road. Available aerial images show the previous reclamation before re-disturbance. The associated production facility was abandoned and reclaimed in June 2021 after the last well was plugged in spring 2021. This reclamation was in the first growing season which had record heat and very little precipitation. However, since a location assessment was already performed, PDC will reseed prior to the Spring growing season. CA complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed:

Title: Senior EHS Coordinator

Date: 2/21/2022 3:46:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files