

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/25/2022

Submitted Date:

02/26/2022

Document Number:

688312266**FIELD INSPECTION FORM**Loc ID: 457751 Inspector Name: Sherman, Susan On-Site Inspection: ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 35080

Name of Operator: GRAND MESA OPERATING CO

Address: 1700 N WATERFRONT PKWY B600

City: WICHITA State: KS Zip: 67206

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hutton, Neil		nhutton@gmocks.com	Designated Anent
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent
Reilly, Pat	316-265-3000	preilly@gmocks.com	Designated Agent
Young, Rob		rob.young@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457750	WELL	PR	11/18/2020	OW	121-11081	The Undeafed 1-7	PR

General Comment:

Spill from Treater Inspection

On 2/25/2022 at approximately 11 am inspector was driving north on CR U and saw that the treater at this location had malfunctioned spraying oil onto the access road and into the CRP (also close to CR U) to the north of the treater. Oil has ran down the outside of the treater from the top. Some free oil was inside the metal berms around the treater. See attached photos. Inspector contacted the operator and the COGCC EPS.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
PW/CO	Treater	<= 1 bbl		
Comment:	Treater malfunctioned (very cold outside temperatures) cause oil to be spilled and sprayed from it (see attached photos).			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 03/04/2022

In Containment: No

Comment: Some oil was inside the berms (<5 bbls) and some was sprayed outside the berms (,1 bbl).

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 457750 Type: WELL API Number: 121-11081 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI for spill

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688312269	Grand Mesa The Undefeated 1-7 treater spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5675361