

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402969618

Date Received:  
03/01/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
TEP	970-285-9377	COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703641  
Inspection Date: 12/08/2021 FIR Submit Date: 12/09/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC Company Number: 10531  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 334708

Location Name: MILLER-67S91W Number: 6SESW County: \_\_\_\_\_  
Qtrqr: SESW Sec: 6 Twp: 7S Range: 91W Meridian: 6  
Latitude: 39.469813 Longitude: -107.599549

FACILITY - API Number: 05-045-00 Facility ID: 334708

Facility Name: MILLER-67S91W Number: 6SESW  
Qtrqr: SESW Sec: 6 Twp: 7S Range: 91W Meridian: 6  
Latitude: 39.469813 Longitude: -107.599549

CORRECTIVE ACTIONS:

1 CA# 158494

Corrective Action: Remove stored equipment. Date: 03/08/2022

Response: CA COMPLETED Date of Completion: 12/15/2021

Operator Comment: The ECD is used as needed to maintain compliance with air emissions. The ECD is NOT unused equipment.  
See attached response.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 158495

Corrective Action: Remove debris

Date: 12/17/2021

Response: CA COMPLETED

Date of Completion: 02/28/2022

Operator  
Comment:

Random debris has been removed. Please cite rule supporting CA.

COGCC Decision:

COGCC  
Representative:

3 CA# 158496

Corrective Action: Remove stained material. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition

Date: 12/24/2021

Response: CA COMPLETED

Date of Completion: 02/28/2022

Operator  
Comment:

Staining under heat trace pump exhaust has been removed.

COGCC Decision:

COGCC  
Representative:

4 CA# 158497

Corrective Action: Install or repair required BMPs

Date: 01/21/2022

Response: CA COMPLETED

Date of Completion: 12/19/2021

Operator  
Comment:

BMPs repaired on 12/19/21.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions completed or addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP Env Lead

Date: 3/1/2022 3:18:59 PM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402969627	ECD response

Total Attach: 1 Files