

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402969678

Date Received:  
03/01/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
TEP 970-285-9377 COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703644  
Inspection Date: 12/08/2021 FIR Submit Date: 12/09/2021 FIR Status:

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC Company Number: 10531  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 383321

Location Name: MILLER-66S91W Number: 31SESE County:  
Qtrqr: SESE Sec: 31 Twp: 6S Range: 91W Meridian: 6  
Latitude: 39.477380 Longitude: -107.588835

FACILITY - API Number: 05-045-00 Facility ID: 383321

Facility Name: MILLER-66S91W Number: 31SESE  
Qtrqr: SESE Sec: 31 Twp: 6S Range: 91W Meridian: 6  
Latitude: 39.477380 Longitude: -107.588835

CORRECTIVE ACTIONS:

1 CA# 158498

Corrective Action: Identify all hazards associated with equipment. Date: 03/08/2022

Response: CA COMPLETED Date of Completion: 01/18/2022

Operator Comment: Separators are not tanks and do not require labels per COGCC rules. See attached response.

COGCC Decision:

COGCC  
Representative:

2 CA# 158499

Corrective Action: Remove stored equipment

Date: 03/08/2022

Response: CA COMPLETED

Date of Completion: 01/18/2022

Operator Comment: The ECD is used as needed to maintain compliance with air emissions from this location. ECD is NOT unused equipment. See attached response.

COGCC Decision:

COGCC  
Representative:

3 CA# 158500

Corrective Action: Install or repair required BMPs

Date: 01/21/2022

Response: CA COMPLETED

Date of Completion: 01/18/2022

Operator Comment: Cut slope is not unstable. Site BMPs are controlling and minimizing sediment as designed. All sediment is contained on pad and BMPs are maintained as needed. See attached response.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed. See attached responses.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP Env Lead

Date: 3/1/2022 3:41:49 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402969697	Separator response
402969698	ECD response
402969699	Cut slope response

Total Attach: 3 Files