

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2022

Submitted Date:

03/08/2022

Document Number:

701102823

**FIELD INSPECTION FORM**

Loc ID 315092 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74740  
Name of Operator: RIO MESA RESOURCES INC  
Address: P.O. BOX 984  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 13 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box
Pesicka, Conor		conor.pesicka@state.co.us	
Hayes, Mike	970-620-2257	hayespetroleum@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230242	WELL	SI	11/01/2021	OW	103-07901	GOVERNMENT 2	SI

**General Comment:**

COGCC Routine Inspection Report Summary  
Location is in a High Priority Habitat Area.  
During this inspection the following compliance issues were observed:

- Local EMS # or 911 not on tank battery sign.
- Tank battery sign doesn't meet Rule 605.e..
- Damaged tank labels.
- No API # on well sign.
- Stormwater and crude oil in well cellar.

Remove free fluids within 24 hours and clean stained ground, cellar ring and well head within 30 days.

- Tank battery berm: Storm water from hillside has wash sediment over back berm. Subsidence of base in front of 80 bbl crude oil tank. Base of berm is marshy.
- Sediment coming off hillside behind tank battery berm and collecting sediment and stormwater in berm. Storm water damage of access road and moving across south end of location. Subsidence of tank ground base. Storm water collected in well cellar.
- Deadman markers not brightly colored.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access road needs maintained. See stormwater report		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Tank battery sign doesn't meet Rule 605.e..		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 06/10/2022
Type	TANK LABELS/PLACARDS		
Comment:	Damaged tank labels.		
Corrective Action:	Install sign to comply with Rule 605.g.		Date: 06/10/2022
Type	WELLHEAD		
Comment:	No API # on well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 06/10/2022
Emergency Contact Number:			
Comment:	Local EMS # or 911 not on tank battery sign.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 04/09/2022
<b>Good Housekeeping:</b>			
Type			
Comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Stormwater and crude oil in well cellar.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Remove free fluids within 24 hours and clean stained ground, cellar ring and well head within 30 days.		Date: 03/08/2022
In Containment: Yes			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	PUMP JACK		
Comment:			

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Deadman markers not brightly colored.		
Corrective Action:	Mark deadmen with bright color.	Date:	04/10/2022

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	<100 BBLS	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient	Base Insufficient	Inadequate
Comment:	Storm water from hillside has wash sediment over back berm. Subsidence of base in front of 80 bbl crude oil tank. Base of berm is marshy.			
Corrective Action:	Maintain tank berm and base.			Date: 04/09/2022

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 230242 Type: WELL API Number: 103-07901 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			
		Ditches	Fail			
				Material Handling And Spill Prevention	Fail	Load line spill pan needs maintained.
Compaction						

Comment: [Sediment coming off hillside behind tank battery berm and collecting sediment and stormwater in berm. Storm water damage of access road and moving across south end of location. Subsidence of tank ground base. Storm water collected in well cellar.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 04/09/2022

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701102826	Inspection 701102823 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5684978">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5684978</a>