

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/14/2022

Submitted Date:

03/14/2022

Document Number:

699503824

FIELD INSPECTION FORM
 Loc ID 320322 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 76859

Name of Operator: SCHREIDER & COMPANY INC

Address: 9227 E LINCOLN AVE SUITE 200

City: LONE TREE State: CO Zip: 80124

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Kelly, George	(602) 697-2484	schneiderco@outlook.com	
Burn, Diana		diana.burn@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203446	WELL	SI	01/01/2018	GW	001-09005	GRETCHEN RAGLUND 2-14	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Berms on location need to be repaired around oil tanks, and fiberglass tank.		
Corrective Action:	Comply with COGCC BMP rules.	Date:	11/24/2021
Type	OTHER		
Comment:	Valve on oil tank is leaking fluid from tank, see pics and video. At time of inspection called emergency number posted on tank batter sign, and line was not active. Contacted COGCC employees to try to find contact number for company. Called George Kelly 602-697-2484 at 2:32 PM MT with no answer, unable to leave message due to full inbox.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.	Date:	03/14/2022
Type	OTHER		
Comment:	no Form 6 on file		
Corrective Action:	Comply with warning letter document # 402937522	Date:	02/09/2022
Type	OTHER		
Comment:	Fencing around equipment needs to be prepared, livestock on owners land.		
Corrective Action:	Comply with COGCC Fencing requirements per 1002a rules.	Date:	11/14/2021
Type	OTHER		
Comment:	weeds unmanaged on location, trash near separator, unused pipe on location, cut off wellhead, risers need to be LOTO from wellhead flowlines and by separator		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	07/17/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Fencing around equipment needs to be repaired.		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			FIBERGLASS AST		,	
Comment:	Tank does not have any signage					
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Berms need to be repaired.			
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Berms need to be repaired			
Corrective Action:				

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 203446 Type: WELL API Number: 001-09005 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: PA

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 3/14/22I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Gretchen Raglund 2-14</p> <p>Company Name- Schreider & Company Inc</p> <p>API- 05-001-09005</p> <p>In Adams County Colorado.</p> <p>While there, I observed PA well</p> <p>This is a follow up inspection from document # 669503332,700900164 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>weeds unmanaged on location, trash near separator, unused pipe on location, cut off wellhead, risers need to be LOTO from wellhead flowlines and by separator</p> <p>Comply with COGCC housekeeping rules 7/17/20</p> <p>Berms on location need to be repaired around oil tanks, and fiberglass tank.</p> <p>Comply with COGCC BMP rules. 11/24/21</p> <p>Fencing around equipment needs to be prepared, livestock on owners land.</p> <p>Comply with COGCC Fencing requirements per 1002a rules. 11/14/21</p> <p>no Form 6 on file</p> <p>Comply with warning letter document # 402937522 2/9/22</p> <p>Valve on oil tank is leaking fluid from tank, see pics and video. At time of inspection called emergency number posted on tank batter sign, and line was not active. Contacted COGCC employees to try to find contact number for company. Called George Kelly 602-697-2484 at 2:32 PM MT with no answer, unable to leave message due to full inbox.</p> <p>Control and contain spills/releases and clean up per Rule 906.a.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	03/14/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503825	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5696010
699503826	video of tank valve leaking	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5696011