

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402981749

Date Received:

03/10/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Murray, Richard</u>		<u>g.richard.murray@state.co.us</u>
<u>Arthur, Denise</u>		<u>denise.arthur@state.co.us</u>
<u>Ramsey, Scott</u>		<u>scott.ramsey@state.co.us</u>
<u>Heil, John</u>		<u>john.heil@state.co.us</u>
<u>Trujillo, Aaron</u>		<u>aaron.trujillo@state.co.us</u>
<u>. Inspections</u>		<u>COGCCInspectionReports@terraep.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800004

Inspection Date: 02/27/2022

FIR Submit Date: 03/08/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335539

Location Name: McPherson Number: A Pad County: _____

Qtrqr: NENW Sec: 16 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.531109 Longitude: -107.675932

FACILITY - API Number: 05-045- -00 Facility ID: 335539

Facility Name: McPherson Number: A Pad

Qtrqr: NENW Sec: 16 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.531109 Longitude: -107.675932

CORRECTIVE ACTIONS:

1  CA# 160054

Corrective Action: Comply with Rule 912.a Spills and Releases: Control and contain spill/releases and clean up per Rule 912.a. Immediately stop and clean up.
24 hours to remove free fluids.
30-days to remove impacted soil.

912.b. Spill Reporting: Report spill or release of E&P waste or produced fluids.
Remove free fluids and Contact COGCC EPS staff per Rule 912.b.
24 hours to remove free fluids.
24 hours for notification and 72 hours for Initial Form 19 Report.

Date: 03/08/2022

Response: CA COMPLETED

Date of Completion: 03/08/2022

Operator Comment: TEP responded immediately to the location upon being notified of a potential spill by Alex Fischer on 3/07/22 at 12:47 p.m.. TEP responded to, and immediately cleaned up the impacted soils on 3/07/22 - 3/08/22. A confirmation soil sample has been collected and will be sent to an analytical lab for full Table 915-1 analysis to ensure that applicable cleanup standards have been met. This incident is not a reportable event per COGCC Rule 912 as described in the attached response that was sent to COGCC staff on 3/07/22.

COGCC Decision: **Not Approved**

COGCC Representative: It is not possible to determine whether the spill was cleaned up without the results from the confirmation soil samples. Per the comments from the Operator it appears that some of the corrective actions have been completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action #160054 has been completed and addressed. See attached response for a full description of initial response and details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Env Lead

Date: 3/10/2022 5:29:35 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402981749	FIR RESOLUTION SUBMITTED
402981767	Correspondence

Total Attach: 2 Files