

# Inspection Photos

API: 073-06774

Operator: KODA EXPLORATION LLC

Inspection Date: 3/24/2022



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06774 | Date: 3/24/2022

## Inspection Photos



**Photo 1.** Facing east at the beginning of the access road. If well is plugged and abandoned the gravel will need to be removed and road will need to be reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06774 | Date: 3/24/2022

## Inspection Photos



**Photo 2.** Facing east along the two track road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06774 | Date: 3/24/2022



## Inspection Photos



**Photo 3.** Facing north toward the fenced location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06774 | Date: 3/24/2022

## Inspection Photos



**Photo 4.** Facing northwest at the location. The location has not been reclaimed per the 1003 Rules. Soils are not protected from erosion and degradation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06774 | Date: 3/24/2022



## Inspection Photos



**Photo 5.** The well remains at center of location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06774 | Date: 3/24/2022

## Inspection Photos



**Photo 6.** Facing toward the area of the pit which was backfilled. Bare soils are susceptible to erosion. Unused areas of the location have not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06774 | Date: 3/24/2022



## Inspection Photos



**Photo 7.** The topsoil pile stored along the perimeter are not protected from erosion and weed infestation. There are undesirable weeds throughout the topsoil piles.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06774 | Date: 3/24/2022



## Inspection Photos



**Photo 8.** There is signs of wind erosion along the topsoil piles which are not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06774 | Date: 3/24/2022