

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10456 Contact Name: Reed Haddock
 Name of Operator: CAERUS PICEANCE LLC Phone: (720) 880-6369
 Address: 1001 17TH STREET #1600 Fax: (303) 565-4606
 City: DENVER State: CO Zip: 80202 Email: rhaddock@caerusoilandgas.com

For "Intent" 24 hour notice required, Name: De Paolo, Corey Tel: (303) 903-8253
COGCC contact: Email: corey.depaolo@state.co.us

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-045-24343-00 Well Number: 14B-35-496
 Well Name: BJU G35 FED
 Location: QtrQtr: SWNE Section: 35 Township: 4S Range: 96W Meridian: 6
 County: GARFIELD Federal, Indian or State Lease Number: COC069557
 Field Name: GRAND VALLEY Field Number: 31290

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.660453 Longitude: -108.134733
 GPS Data: GPS Quality Value: 1.5 Type of GPS Quality Value: _____ Date of Measurement: 06/07/2021

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: 3042

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: While running surface casing on the BJU G35 FED 14B-35-496 the parasite string parted. Caerus attempted to pull the parasite string out of hole without success. Without the use of the parasite string, we would be unable to drill the production hole without losing the wellbore. Caerus decided to plug back the wellbore. Caerus has verbal approval from the BLM and State to plug back the BJU G35 FED 14B-35-496. Caerus cemented the casing in place from the DV tool (899') back to surface with 12.0 ppg cement and topped off the well with tubing behind casing. Caerus will place 5 bbls cement inside casing above the DV tool @ 899' and 150' cement plug inside casing at surface.

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

--

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
CONDUCTOR	30	20	A252	54#	0	100	218	100	0	VISU
SURF	14+3/4	9+5/8	J55	36#	0	2981	1313	2981	0	VISU

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 13 sks cmt from 899 ft. to 834 ft. Plug Type: CASING Plug Tagged:
 Set 32 sks cmt from 157 ft. to 0 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 (Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set 5 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____
 Surface Plug Setting Date: _____ Cut and Cap Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Reed Haddock
 Title: Regulatory Lead Date: _____ Email: rhaddock@caerusoilandgas.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

COA Type	Description

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402996306	CEMENT BOND LOG
402996308	OTHER
402996310	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)