

TEP
RMV 206-20
Location # 335217



location



Lack of stabilization/compaction



TEP
RMV 206-20
Location # 335217



Lack of stabilization/compaction



Stored equipment

