

TEP
RWF 534-20
Location # 335295



location



location

TEP
RWF 534-20
Location # 335295



Valve missing cap/plug



Lack of stabilization/compaction

TEP
RWF 534-20
Location # 335295



Lack of stabilization/compaction



Lack of stabilization/compaction