

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2022

Submitted Date:

03/22/2022

Document Number:

690900197

FIELD INSPECTION FORM

Loc ID: 324591 Inspector Name: FISCHER, ALEX On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	ALL INSPECTIONS
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465486	NEW	AC	11/19/2020		-	Dwinell Tank Battery	EI

General Comment:

On March 18, 2022, COGCC Environmental Staff (Alex Fischer) conducted a field inspection of KP Kauffman Company Inc's (KPK) Dwinell (Location ID: 324591). The inspection was a follow up to Spill ID 473059 and REM 15326. Weather was sunny, temperature about 5 degrees Fahrenheit, and snow cover on the ground. For the most recent environmental field inspection report of this facility, please refer to Document #690900195.

The following is a summary:

County Road 8B was inaccessible from the cattle guard approximately 430' from County Road 8 to the Dwinell facility due to drifted snow. Operator in violation of Rules 204 and 603.I.

Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.

Location

Lease Road:			
Type	Main		
comment:	County Road 8B was inaccessible from the cattle guard approximately 430' from County Road 8 to the Dwinell facility due to drifted snow.		
Corrective Action:	Repair and maintain lease road to comply with rule 204 and 603.I.	Date:	04/22/2022

Overall Good:

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

Flaring:

Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

Inspected FacilitiesFacility ID: 465486 Type: NEW API Number: - Status: AC Insp. Status: EI**COGCC Comments**

Comment	User	Date
<p>On March 18, 2022, COGCC Environmental Staff (Alex Fischer) conducted a field inspection of KP Kauffman Company Inc's (KPK) Dwinell (Location ID: 324591). The inspection was a follow up to Spill ID 473059 and REM 15326. Weather was sunny, temperature about 5 degrees Fahrenheit, and snow cover on the ground. For the most recent environmental field inspection report of this facility, please refer to Document #690900195.</p> <p>The following is a summary: County Road 8B was inaccessible from the cattle guard approximately 430' from County Road 8 to the Dwinell facility due to drifted snow. Operator in violation of Rules 204 and 603.I. Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.</p>	fischera	03/22/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402991667	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5700600
690900198	KPK Dwinell TB Loc 324591, Spill 473059 REM 15326 20220318 Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5700599