

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402998047

Date Received:

03/29/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Recipient, Single

Inspections@catamountep.com

Price, Andrew

918-260-8324

aprice@arkomaops.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693904045

Inspection Date: 12/22/2021

FIR Submit Date: 01/05/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 306801

Location Name: IGE Number: 103 County: LA PLATA

Qtrqtr: NWNE Sec: 8 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122600 Longitude: -107.737010

FACILITY - API Number: 05-067- -00 Facility ID: 267053

Facility Name: OLSON Number: 1A

Qtrqtr: NWNE Sec: 8 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122600 Longitude: -107.737010

CORRECTIVE ACTIONS:

1 CA# 159055

Corrective Action: -Stormwater controls need to be installed to stabilize erosion within the project area by 3/15/2022. Corrective action date is extended to accomodate frozen soil conditions.

Date: 03/15/2022

Response: CA COMPLETED

Date of Completion: 03/18/2022

Operator Comment: Perform repairs and maintenance to Olson 1A and IGE 103 location as per COGCC write up. Cleanup edges of road from wash out. Clean up and place 2-4" rip rap on erosion channel coming off location. Establish ditches down edge of road to keep water from running down center of access road. Remove existing thistle from around pad area. Place and compact roadbase material on access road to location to establish crown on access road

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Perform repairs and maintenance to Olson 1A and IGE 103 location as per COGCC write up. Cleanup edges of road from wash out. Clean up and place 2-4" rip rap on erosion channel coming off location. Establish ditches down edge of road to keep water from running down center of access road. Remove existing thistle from around pad area. Place and compact roadbase material on access road to location to establish crown on access road

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 3/29/2022 1:41:02 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

| | |
|-----------|----------------------------------|
| 402998068 | Olson 1A and IGE 103 FIRR 3-2022 |
|-----------|----------------------------------|

Total Attach: 1 Files