

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402998042

Date Received:

03/29/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 5 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690900195

Inspection Date: 02/10/2022

FIR Submit Date: 02/16/2022

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 324591

Location Name: DWINELL-610N79W Number: 23NESW County: _____

Qtrqr: NESW Sec: 23 Twp: 10N Range: 79W Meridian: 6

Latitude: 40.821920 Longitude: -106.232630

FACILITY - API Number: 05-057- -00 Facility ID: 324591

Facility Name: DWINELL-610N79W Number: 23NESW

Qtrqr: NESW Sec: 23 Twp: 10N Range: 79W Meridian: 6

Latitude: 40.821920 Longitude: -106.232630

CORRECTIVE ACTIONS:

1 ☒ CA# 159727

Corrective Action:

Comply with Rule 606.
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.
Properly dispose of oily waste in accordance with 905.e.

Date: 02/23/2022

Response: CA COMPLETED

Date of Completion: 03/22/2022

Operator
Comment:

Oil on ground surface at load out valve spill containment have been removed. Broken load line bucket has been replaced. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Provide final disposition of the removed oily impacted material.

2 ☒ CA# 159728

Corrective Action: Comply with Rule 606.
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.
Properly dispose of oily waste in accordance with 905.e.

Date: 02/23/2022

Response: CA COMPLETED Date of Completion: 03/22/2022

Operator Comment: Broken load line bucket has been replaced. Please see attached pictures.

COGCC Decision: Approved via an AMI

COGCC Representative:

4 ☒ CA# 159730

Corrective Action: Comply with Rule 606.

Date: 03/02/2022

Response: CA COMPLETED Date of Completion: 03/22/2022

Operator Comment: Trash have been removed from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

5 ☒ CA# 159731

Corrective Action: See previous inspections.

Date: 03/09/2022

Response: CA COMPLETED Date of Completion: 03/22/2022

Operator Comment: Unused 500 bbl tank labeled out of service has been removed from location

COGCC Decision: Approved pending re-inspection

COGCC Representative: Provide location that the out of service tank was moved to.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 3/29/2022 1:41:29 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402998042	FIR RESOLUTION SUBMITTED
402998072	New bucket PIC

Total Attach: 2 Files