

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2022

Submitted Date:

03/31/2022

Document Number:

700901095**FIELD INSPECTION FORM**Loc ID 320063 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10695Name of Operator: BEHRENS RESOURCES INCAddress: PO BOX 188City: DEER TRAIL State: CO Zip: 80135**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		KHuck@adcogov.org	
		GDean@adcogov.org	
Behrens, Vic	303-810-6382	behrens@netecin.net	Inspections
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202471	WELL	SI	06/01/2018	OW	001-07876	LISCO 14-32	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: [Emergency contact Sign not updated to reflect current operator](#)Corrective Action: [Emergency contact Sign not updated to reflect current operator. Install sign to comply with Rule 605.g. 30 days if missing 24 hour operator contact number and/or local emergency contact. Corrective Action date 4/29/2022.](#)Date: 04/29/2022**Good Housekeeping:**

Type	TRASH		
Comment:	Trash throughout location		
Corrective Action:	.Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 4/15/2022. See attached photo #1 through 9.		Date: <u>04/15/2022</u>
Type	DEBRIS		
Comment:	Dead weed/ debris throughout location		
Corrective Action:	Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 4/15/2022. See attached photo #1 through 9.		Date: <u>04/15/2022</u>
Type	WEEDS		
Comment:	Weeds throughout location		
Corrective Action:	Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 4/15/2022. See attached photo #1 through 9.		Date: <u>04/15/2022</u>

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Plunger Lift	# 1		
Comment:	Old valve in well head leaking gas.		
Corrective Action:	Mechanical Conditions. Old valve in well head leaking gas. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. 15 days. If leak is found immediately call to operator 24 hours to fix the leak or isolate leak. Corrective Action Date 4/2/2022. See attached photo #10.		Date: <u>04/02/2022</u>
Type: Bird Protectors	# 2		
Comment:	Wildlife netting not completely covering open top tank and multiple holes in netting		
Corrective Action:	902.b. Wildlife netting not completely covering open top tank and multiple holes in netting. Install or repair wildlife protection equipment. Corrective Action date 4/15/2022. See attached photo #2.		Date: <u>04/15/2022</u>
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		

Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.790823,-104.515307
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Adequate
Comment:	Shears berm with crude			
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
001-08052
001-07876

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202471 Type: WELL API Number: 001-07876 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appers to be plumbed to surface

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday March 30, 2022at approximately 12:45pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection at C Lisco 14-32, Behrens Resources, at API # 001-07876 in Adams County Colorado.</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Dead Weeds, trash and debris throughout location. Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 4/15/2022. See attached photo #1 through 9.</p> <p>Mechanical Conditions. Old valve in well head leaking gas. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. 15 days. If leak is found immediately call to operator 24 hours to fix the leak or isolate leak. Corrective Action Date 4/2/2022. See attached photo #10.</p> <p>Emergency contact Sign not updated to reflect current operator. Install sign to comply with Rule 605.g. 30 days if missing 24 hour operator contact number and/or local emergency contact. Corrective Action date 4/29/2022.</p> <p>902.b. Wildlife netting not completely covering open top tank and multiple holes in netting. Install or repair wildlife protection equipment. Corrective Action date 4/15/2022. See attached photo #2.</p> <p>A message was left on a voice mail at 15:30pm on 3/30/2022 regarding multiple leaks on multiple locations.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	03/31/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700901096	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5711287