

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2022

Submitted Date:

03/29/2022

Document Number:

696203532

## FIELD INSPECTION FORM

 Loc ID 453726 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 10163  
 Name of Operator: NONSUCH NATURAL GAS INC  
 Address: P O BOX 110066  
 City: NAPLES State: FL Zip: 34108
**Findings:**

- 5 Number of Comments  
 4 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Lee, David	239-289-9046	dlee@nng.us.com	
		denise.arthur@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453727	TANK BATTERY	AC	01/12/2018		-	CSOC 697-14 Tank Battery	RI

**General Comment:**

On 03/28/2022, Reclamation Specialist Trujillo inspected Nonsuch Natural Gas Inc's CSOC TB Location in Garfield County, Colorado.

This inspection is a followup to:

- #696201797 dated 9/16/2020;
- #696201822 dated 9/24/2020;
- #696201988 dated 11/02/2020;
- #696202916 dated 7/12/2021;
- #696203087 dated 8/23/2021;

and #696203324 dated 11/1/2021 to document compliance with the following corrective actions:

- Unused or unneeded equipment on the Location
- Good Housekeeping
- Stormwater
- Wildlife Protection measures

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions.

Refer to the "Good Housekeeping", "Equipment", "Reclamation", "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	<p>Previous inspections documented unused pipe equipment stored behind the methanol tank. Inspections required Operator to comply with Rule 606 and remove unused equipment</p> <p>It was observed in this inspection that the various unused pipe and honeypot remains improperly stored on the Location, behind the methanol tank.</p> <p>This corrective action has not been addressed and remains applicable.</p>		
Corrective Action:	Comply with Rule 606 and remove unused equipment.	Date:	11/10/2020
Type	UNUSED EQUIPMENT		
Comment:	<p>Previous inspections documented equipment on the Location (200 bbl tank, 500 gallon methanol tank, separator) that did not appear to be active, or necessary for production activities on the Location.</p> <p>Operator was required to submit a Form 4 sundry with records identifying equipment's current status and use for production on the Location by 10/2/2020.</p> <p>Inspection #696203087 noted that Operator failed to submit the documentation and required Operator to comply with Rule 606.a and remove unused equipment from the Location.</p> <p>It was observed in this inspection that the equipment remains on the Location; no documentation has been submitted by Operator identifying current status/use on Location.</p>		
Corrective Action:	Comply with Rule 606 and remove equipment not necessary for use on the Location.	Date:	10/02/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Bird Protectors	# 2		
Comment:	<p>Previous inspections observed that protection equipment to prevent wildlife access to the secondary containment BMP at the 500 gallon Methanol tank, and the Separator stack were missing or inadequate. Inspection Required Operator to install or repair wildlife protection equipment by 7/18/2021.</p> <p>It was observed in this inspection that protection equipment to prevent wildlife access to the secondary containment BMP at the tank, and separator remain missing or inadequate.</p>		
Corrective Action:	Install or repair wildlife protection equipment	Date:	07/18/2021

**Venting:**

Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 453727 Type: TANK API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

**Comment:** Previous inspections observed that BMPs to protect and stabilize unpaved areas of the Location and access road, and to allow for proper stormwater discharge are missing, or insufficient; stormwater runoff resulted in erosion degradation and offsite sediment discharge at Location entrance and access road. Inspection required Operator to comply with Rule 1002.f.(2)C.

Snow cover prevented an accurate assessment of stormwater management on the Location; however, no Resolution Form has been submitted by Operator documenting that the corrective action has been addressed; control measures appear to remain missing or insufficient on sections of the access road that was visible; degradation remains evident.

**Corrective Action:** Install or repair required BMPs per Rule 1002.f.(2)C. Ensure control measures are installed in accordance with good engineering practices, and maintained in proper functioning condition.

**Date:** 07/20/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402998005	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5707259">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5707259</a>
696203533	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5707257">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5707257</a>