

LARAMIE ENERGY LLC
Horseshoe Canyon 3-19 Pad
Location: 312623



Tank has bullet damage and staining from seeping bullet holes.



LARAMIE ENERGY LLC
Horseshoe Canyon 3-19 Pad
Location: 312623



Tank has bullet damage and staining from seeping bullet holes. No fluid was noticed but several inches of solids in bottom of tank.

LARAMIE ENERGY LLC
Horseshoe Canyon 3-19 Pad
Location: 312623



Road ditches are washing and sediment moving.



Storm water rills crossing roadway.