

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2022

Submitted Date:

04/06/2022

Document Number:

696203547

FIELD INSPECTION FORMLoc ID 324459 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Johnston, Tyson		Tyson.Johnston@oxbow.com	
Lang, Heather		Heather.Lang@oxbow.com	
,		geops@oxbow.com	Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324459	LOCATION	AC			-	FEDERAL-610S90W 32SWSE	RI

General Comment:

On 4/4/2022 Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Gunnison Energy's Federal 10-90-32 location in Gunnison County, Colorado.

The following compliance issues were observed during this inspection:

- Storage of unnecessary equipment
- Stained Soils
- Pad stabilization
- Interim Reclamation and Surface Disturbance Minimization

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	<p>Inspection #696203162 observed trailer equipment/Equipment not necessary for production observed stored on the Location and inteirm areas of the Location. Inspection required Operator to comply with Rule 606 by 10/13/2021.</p> <p>It was observed that the stored equipment has been removed from the Location. CA has been addressed.</p> <p>Submit FIRR "CA Complete".</p>		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
Comment:	<p>Inspection #696203162 observed stained soils observed on production area, and areas southwest of the well. Inspection required Operator to clean up impacted soils by 10/28/2021.</p> <p>Unable to determine if corrective action has been addressed due to snow cover; no Resolution has been submitted stating CA has been addressed.</p> <p>CA will remain applicable; a followup inspection will be conducted to determine compliance.</p>			
Corrective Action:	Clean up impacted soils per Rule 912.a. and remediate to Table 915-1 Cleanup Concentrations; for non-E&P waste comply with Rules 906.a-d			Date: 10/28/2021

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Inspection #696203162 observed that vehicle travel, and storage of vehicles/trailers/equipment on the interim and off-site areas of the Location resulted in additional degradation and disturbance. Inspection required Operator to reclaim disturbed areas by 11/15/2021.

Unable to determine if corrective action has been addressed due to snow cover; no Resolution has been submitted stating CA has been addressed.

CA will remain applicable and a followup inspection will be conducted to determine compliance with 1003 rules.

Corrective Action **Comply with 1003 rules.**Date **11/15/2021**

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696203162 observed that control measures to stabilize the production area, and to minimize tracking area missing or insufficient; vehicle rutting, tracking and degradation observed on pad and location entrance. Inspection required Operator to comply with 1002.f by 10/5/2021.

Unable to determine if corrective action has been addressed due to snow cover; no Resolution has been submitted stating CA has been addressed.

CA will remain applicable and a followup inspection will be conducted to determine compliance with 1002.f.

Corrective Action: **Comply with Rule 1002.f**

Date: 10/05/2021

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203548	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5716058