



E. Stieber April 5, 2022

MarCom Photo Template

4/5/2022 - Pooled Liquids from Release.



20220406.jpg

View looking West

4/5/2022 - Hydrovac Removing Liquids



20220406_(10).jpg

View looking North

4/5/2022 - Broken HDPE Line



20220406_(11).jpg

Release Location

4/5/2022 - Broken HDPE Line



20220406_(12).jpg

Release Location

4/5/2022 - Pooled Liquids



20220406_(2).jpg

View looking East. Hydrovac removing liquids.

4/5/2022 - Pooled Liquids



20220406_(3).jpg

View looking NE

4/5/2022 - Pooled Liquids



20220406_(4).jpg

View looking North

4/5/2022 - Pooled Liquids



20220406_(5).jpg

View looking North

4/5/2022 - Release Location



20220406_(6).jpg

View looking West

4/5/2022 - Release Location



20220406_(7).jpg

View looking West

4/5/2022 - Release Location



20220406_(8).jpg

View looking NW

4/5/2022 - Pooled Liquids



20220406_(9).jpg

View looking North
