

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2022

Submitted Date:

04/07/2022

Document Number:

691201577

FIELD INSPECTION FORMLoc ID 467698 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Spills&Remediations		COGCCSpillRemediation@pdce.com	
Inspections, All		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481729	SPILL OR RELEASE	CL	03/17/2022		-	Booth 25-32	EI

General Comment:

This is an environmental inspection of spill 481729 and remediation 21296. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Orange construction fencing surrounding excavation.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Inadequate		
Comment	Impacted soils on location with no liner or stormwater BMPs.			
Corrective Action	Operator shall install controls to protect stormwater runoff as soon as practicable. Prior to the closure of the remediation, Operator will collect soil samples the area where impacted soils were installed.			Date:

Spill/Remediation:

Comment:	
Corrective Action:	Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201578	Soils Piles	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5717197
691201579	Excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5717198