

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402968569

Date Received:
02/28/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10773
Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC
Address: 90 MOONRISE COURT
City: ERIE State: CO Zip: 80516

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Smith, Sydney</u>	<u>303-910-4511</u>	<u>ssmith@fundareresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693700907
Inspection Date: 12/22/2021 FIR Submit Date: 12/30/2021 FIR Status: _____

Inspected Operator Information:

Company Name: WHITING OIL & GAS CORPORATION Company Number: 96155
Address: 1700 LINCOLN STREET SUITE 4700
City: DENVER State: CO Zip: 80290

LOCATION - Location ID: 444465

Location Name: Razor Number: 25O Pad County: _____
Qtrqtr: SWSE Sec: 25 Twp: 10N Range: 58W Meridian: 6
Latitude: 40.803461 Longitude: -103.810306

FACILITY - API Number: 05-123-00 Facility ID: 444465

Facility Name: Razor Number: 25O Pad
Qtrqtr: SWSE Sec: 25 Twp: 10N Range: 58W Meridian: 6
Latitude: 40.803461 Longitude: -103.810306

CORRECTIVE ACTIONS:

2 CA# 158980

Corrective Action: Operator to provide COGCC Engineering Integrity Group with root cause analysis for flowline failure. Operator to remove waste storage area and backfill excavations. Submit FIRR with disposal documentation and backfill photo documentation.

Date: 02/28/2022

Response: CA COMPLETED Date of Completion: 02/22/2022

Operator Comment: The root cause of the failure was determined to be due to bacteria. Fundare has future plans to replace the lines.

COGCC Decision: **Not Approved**

COGCC Representative: Operator root cause is inadequate to describe preventative measures to cease bacterial problems and describe details of flowline replacement (material, schedule, and locations) to prevent future releases. This Corrective Action is not approved and Operator is directed to contact COGCC Engineering Integrity Group as directed in original inspection.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sydney Smith

Signed: _____

Title: Manager EHSR

Date: 2/28/2022 8:58:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402968569	FIR RESOLUTION SUBMITTED
402968573	Photo Documentation

Total Attach: 2 Files