

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2022

Submitted Date:

04/12/2022

Document Number:

700600374**FIELD INSPECTION FORM**Loc ID 308184 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263851	WELL	PR	07/12/2007	GW	071-07641	VIKING 34-15	EI

**General Comment:**

COGCC Environmental inspection found evidence of a spill of an unknown volume from wellhead. Soil around pumpjack has salt impacts. See attached photos.

Pit walls are inadequate on southeast side of pit.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Drip leak. Wellhead is actively leaking.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 04/13/2022

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	Produced water spill from wellhead has left a salt impacted area around the wellhead. See attached photos.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Remove impacted soil from location to prevent transport of impacts of location.			Date: 05/12/2022

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat:

Long:

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment: Southeast pit wall is inadequate to keep water inside pit.

Corrective Action:

Bring pit into compliance by repairing pit walls or deepening pit or submit Form 27 for pit closure.

Date: 05/12/2022**Fencing:**Fencing Type: WildlifeFencing Condition: Inadequate

Comment: Fencing is in disrepair. See attached photos

Corrective

Repair fencing.

Date: 05/12/2022**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	265467	1121073	
	265467	1121073	

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
700600375	Inspection photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721342">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721342</a>