



- Photo 1 –





- Photo 2 – Bucket with waste oil hanging off wellhead piping





- Photo 3 – Minor oil stained soil south of wellhead





- Photo 4 – Oil stained soil in motor shed





- Photo 5 – Drum of corrosion inhibitor with no secondary containment





- Photo 6 – Drum of corrosion inhibitor with no secondary containment