

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/13/2022

Submitted Date:

04/21/2022

Document Number:

688000639

FIELD INSPECTION FORM
 Loc ID 330667 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
330667	LOCATION	AC			-	D.O.C. SHOWERS-68N60W 32NWSW	EI

General Comment:

Environmental inspection related to Rem #17544 and Rem #11274. Both projects require additional data to be provided to COGCC before they can be closed.

Environmental**Spill/Remediation:**

Comment: Additional boron data was to be supplied for Rem #17544 and Rem 11274 had a COA for assessment at the skim tank location and soil suitability parameters confirmed in the SS07 - SS10 area.

Corrective Action: Provide supplemental Form 27 updates with the requested information.

Date: 05/20/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000640	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5730739