

Inspection Photos

4/22/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335594

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335594



Photo 1: Photo taken from the disturbed slopes on the north end of the Location. Photo example showing hydromulch (yellow arrow) implemented by Operator has not been maintained in a proper functioning condition to minimize erosion, degradation, and to stabilize the slopes; erosion and degradation to the slopes have persisted.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335594



Photo 2: Photo taken from the disturbed slopes on the north end of the Location. Photo example showing hydromulch (yellow arrow) implemented by Operator has not been maintained in a proper functioning condition to minimize erosion, degradation, and to stabilize the slopes; erosion and degradation to the slopes have persisted.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335594



Photo 3: Photo taken from the disturbed slopes on the north end of the Location. Photo example showing hydromulch (yellow arrow) implemented by Operator has not been maintained in a proper functioning condition to minimize erosion, degradation, and to stabilize the slopes; erosion and degradation to the slopes have persisted. Red arrow shows areas where soils have eroded and covered sections of the hydromulch

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335594



Photo 4: Photo taken from the disturbed slopes on the north end of the Location. Photo example showing hydromulch (yellow arrow) implemented by Operator has not been maintained in a proper functioning condition to minimize erosion, degradation, and to stabilize the slopes; erosion and degradation to the slopes have persisted. Red arrow shows areas where soils have eroded and covered sections of the hydromulch