

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2022

Submitted Date:

04/26/2022

Document Number:

696203603

**FIELD INSPECTION FORM**
 Loc ID 335822 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kirschner, Steven		steven.kirschner@state.co.us	
,		COGCC.inspections@caerus oilandgas.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335822	LOCATION	AC			-	N. PARACHUTE-65S95W 28NWNW	RI

**General Comment:**

On 4/22/2022, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Caerus Piceance's PARACHUTE-65S95W /28NWNW location in Garfield County, Colorado.

This inspection is a followup to 696202448 dated 3/9/2021 to document compliance with the following corrective actions:

- 1003 Interim reclamation
- 1002.f Stormwater

Per Hearing Order No. 1-258, the Commission granted Caerus a waiver to comply with interim reclamation requirements of Rule 1003; corrective action from inspection 696202450 requiring compliance with 1003 Rules is no longer applicable.

Per Hearing Order No. 1-258, the Commission's grant of a waiver of further compliance with Rule 1003 does not relieve Caerus of its obligation to control stormwater in accordance with Rule 1002.f.

The following compliance issues were observed during this inspection:

- 1002.f

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See "COGCC Comments".](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 05/06/2022

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<b>STORMWATER COMMENTS</b>  It was observed in this inspection that work appears to have been conducted to address the 1002.f corrective action from inspection #696202448; the stormwater diversion ditch along the northern perimeter has been regraded to match the adjacent upslope areas, and Operator appears to have implemented hydromulch to the bare interim areas on the north end of the Location; unable to find a FIRR submitted by Operator stating corrective action was completed per 210.b.  It was observed in this inspection that control measures to minimize erosion, degradation, and to stabilize the slopes on the north end of the Location, as well as the slopes of the ditch, are missing or insufficient; control measures previously applied (hydromulch) have not been maintained in a proper functioning condition by Operator, and is no longer adequate. Unable to find evidence that control measures to minimize erosion, degradation, and to stabilize the slopes of the ditch were been implemented upon regrading of the ditch- BMPs are currently missing or insufficient at slopes of the ditch.  Erosion, degradation and stabilization issues at the slopes have persisted.	trujilloam	04/26/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203604	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735963">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735963</a>