



CAUTION
ENTERING
ELECTRICALLY CLASSIFIED AREA
INTRINSICALLY SAFE EQUIPMENT ONLY
HOT WORK PERMIT REQUIRED FOR
WELDING, CUTTING, GRINDING, BURNING,
OR ANY OTHER WORK THAT COULD PRODUCE A SPARK. WORK
USING ELECTRICAL TOOLS ON EQUIPMENT
REQUIRES A SPECIAL PERMIT.

KerrMcGee
OIL & GAS ONSHORE LP
CHEESMAN 38C-28HZ
NENE SEC 28-T3N-R65W
IN CASE OF EMERGENCY CALL
870-515-1500