

Inspection Photos

5/2/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334752

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334752



May 2, 2022
39.41263729N 108.04514725W



May 2, 2022
39.4126366N 108.04515002W

Photo 1: Photos taken from the north end of the Location. Photos 1-2 provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334752



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334752



Photo 3: Photo taken from the west side, of the southwestern produced water tank; leak observed at the bull plug. Photo also shows stained soils observed within the tank battery.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334752



Photo 4: Photo example showing additional stained soils observed at the tank battery.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334752



Photo 5: Photo taken from the cut slopes on the north end of the Location. Control measures to minimize erosion missing or insufficient at the cut slopes; erosion degradation observed.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 334752



Photo 6: Photo taken from the cut slopes on the north end of the Location. Control measures to minimize erosion missing or insufficient at the cut slopes; erosion degradation observed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334752



May 2, 2022
39.41246754N 108.04578899W



May 2, 2022
39.41246939N 108.04578935W

Photo 7: Photos taken from the western interim areas of the Location, facing north. Photos show interim areas that appear to have been recently disturbed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334752



Photo 8: Photo taken from the interim areas on the west end of the Location. Photo shows control measures to minimize erosion are missing or insufficient; erosion degradation observed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334752



Photo 9: Photo taken from the interim areas on the west end of the Location. Photo shows control measures to minimize erosion are missing or insufficient; erosion degradation observed. Arrow showing sediment deposition due to erosion degradation on the interim areas.