

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/26/2022

Submitted Date:

04/27/2022

Document Number:

693904443

FIELD INSPECTION FORM

Loc ID 306896 Inspector Name: ROY, CATHERINE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274639	WELL	PR	12/01/2021	GW	067-08991	GOEGLEIN 2	RI

General Comment:

On 4/26/2022 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

- Assess and maintain stormwater controls. Additional BMPs need to be installed where existing controls are not adequate. Corrective action date: 5/27/2022

See below, and attached photos for additional detail.

Inspected Facilities

Facility ID: 274639 Type: WELL API Number: 067-08991 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater controls are installed in response to 2020 reclamation inspection. However, BMPs are full of sediment and needing maintenance. Additional BMPs appear needed at discharge points within the project area.](#)

Corrective Action: [-Assess and maintain stormwater controls. Additional BMPs need to be installed where existing controls are not adequate. Corrective action date: 5/27/2022](#)

Date: 05/27/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403029770	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736963
693904444	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736947