

# Inspection Photos

API: 071-09918

Operator: BNL (ENTERPRISE) INC

Inspection Date: 5/5/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09918 | Date: 5/5/2022

Inspection Photos



**Photo 1.** Facing north along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09918 | Date: 5/5/2022

## Inspection Photos



**Photo 2.** Facing west toward the location. Well sign is posted at the location. The location is fenced however there is no gate to restrict livestock access.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09918 | Date: 5/5/2022

## Inspection Photos



**Photo 3.** Southeast side of the location facing west. The disturbed soils around the location are mostly bare of vegetation and will need to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09918 | Date: 5/5/2022

## Inspection Photos



**Photo 4.** The silt fence at the southeast corner is in need of maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09918 | Date: 5/5/2022

## Inspection Photos



**Photo 5.** Facing west. There are wattles installed along the perimeter swale.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09918 | Date: 5/5/2022

## Inspection Photos



**Photo 6.** Facing toward the topsoil stock pile. There is blanket installed along the sides however the entire topsoil pile needs to be protected and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09918 | Date: 5/5/2022

## Inspection Photos



**Photo 7.** Southwest side of the location facing north. There are wattles installed along the perimeter swale.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09918 | Date: 5/5/2022

Inspection Photos



**Photo 8.** There is a black tarp that remains where the well was drilled.



## Inspection Photos



**Photo 9.** There are oil stained soils at the wellhead that needs to be cleaned up. The open top culvert and wellhead needs to be cover and protected to prevent wildlife entry.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09918 | Date: 5/5/2022