

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/26/2022

Submitted Date:

04/28/2022

Document Number:

694500403

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10396  
Name of Operator: SWN PRODUCTION COMPANY LLC  
Address: P.O. BOX 12359  
City: SPRING State: TX Zip: 77389

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone | Email                    | Comment |
|-----------------|-------|--------------------------|---------|
| Snowden, Russ   |       | Russ_Snowden@swn.com     |         |
| Gee, Liz        |       | liz_gee@swn.com          |         |
| Fischer, Alex   |       | alex.fischer@state.co.us |         |
| Maneotis, Karen |       | Karen_Maneotis@swn.com   |         |

**General Comment:**

On 4/26/2022 COGCC staff, Kris Neidel inspected Facility 427370 Conditions were; dry, 60 degrees, part cloudy. This Pit was closed as part of Remediation 17848. The liner was removed. The Pit area was observed for signs of failed liner and or staining, none was observed. The anchor trench portion of the line is still in place. CORRECTIVE ACTION: The Liner Anchor shall be removed and disposed, NONE of liner pieces shall be buried. See Attached Photos.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |  |                         |
|--------------------|--|--|-------------------------|
| Type               | DEBRIS   |  |                         |
| Comment:           | The Pit area was observed for signs of failed liner and or staining, none was observed. The anchor trench portion of the line is still in place. |  |                         |
| Corrective Action: | CORRECTIVE ACTION: The Liner Anchor shall be removed and disposed, NONE of liner pieces shall be buried. See Attached Photos.                    |  | Date: <u>05/28/2022</u> |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description             | URL   |
|--------------|-------------------------|---|
| 403033081    | INSPECTION<br>SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739716</a> |
| 694500404    | photo                   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739702">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739702</a> |